
Cut perimeter of front/back
Finished profile
Scrollsaw inner waste
B
18°
1/4" shaft hole
G
1/2" fill hole location (back face A only)
C
1/4" shaft hole
1/2" hole, 1/2" deep
F
1/2" dispenser hole
Grain
5"
18°
5 1/2"
Arrowhead and Feathers
D
1/4" hole, 3/4" deep
3 1/2"
1/8" hole
1/4" hole
E
1 1/2"